


1


2

B

B




NOT FIELD SERVICEABLE.
 These Rotary Unions can be
 factory refurbished at any
 authorized Vektek repair
 facility.



A

A

1	2	39000050	O-RING, (-204)
No.	QTY	PART No.	DESCRIPTION

PARTS LIST	 VEKTEK VEKTEK, INC. 1334 E. SIXTH AVE. P.O. BOX 625 EMPORIA, KS. 66801 U.S.A.	
	ASSEMBLIES AFFECTED	PARTS LIST, PL, ASSY, HDx UNION, DP
32-2242-04	SIZE A	PL3213
32-2262-04	REV A	REV A

A	5302	RELEASE	NPETERS	5/6/24
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY:	NPETERS	DRAWING STATUS: Released PRODUCTION APPROVED FOR RELEASED STATUS ONLY		
DATE:	5/6/24			

1

2

FORM FEG035_PL_ASIZE, REV. B

SHEET 1 OF 1