


1


2

B

B




NOT FIELD SERVICEABLE.  
 These Rotary Unions can  
 be factory refurbished at  
 any authorized  
 Vektek repair facility.



A

A

1	4	39000050	O-RING, (-204)
No.	QTY	PART No.	DESCRIPTION

<b>PARTS LIST</b>	 <b>VEKTEK</b> VEKTEK, INC. 1334 E. SIXTH AVE. P.O. BOX 625 EMPORIA, KS. 66801 U.S.A.	
	ASSEMBLIES AFFECTED	PARTS LIST, PL, ASSY, HDx UNION, OP
32-4244-02	SIZE A	PL3214
32-4264-02	REV A	REV A

A	5302	RELEASE	NPETERS	5/6/24
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY:	NPETERS	<b>DRAWING STATUS: Released</b> PRODUCTION APPROVED FOR RELEASED STATUS ONLY		
DATE:	5/6/24			

1

2

SHEET 1 OF 1