



LUBRICATE ALL SEALS WITH CLEAN HYDRAULIC OIL PRIOR TO ASSEMBLY.
DO NOT USE SILICONE BASED LUBRICANTS.



PLATE
NON-REPLACEMENT PART



No.	QTY	PART No.	DESCRIPTION	Repair Kit	NOTED
N/A	N/A	62708003	REPAIR KIT		
5	6	39010061	BU RING, (-010)		X
4	3	39000039	O-RING, (-014)		X
3	6	31050012	DIFFUSER, DISK, SAE 4		X
2	3	31050009	FILTER, DISC, SAE 4, 25 MICRON		X
1	3	23002017	RETAINING RING, INTERNAL, 10 MM		X

PARTS LIST



VEKTEK, INC.
1334 E. SIXTH AVE. P.O. BOX 625
EMPORIA, KS. 66801 U.S.A.

ASSEMBLIES AFFECTED

PARTS LIST, PLATE, FILTERED, COMBO SEQ-PRV, METRIC

47-0842-01

L7-0842-01

SIZE
A

MPLV7242

REV
A

SHEET 1 OF 1

A	3538	RELEASE	JDW	07/17/18
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY:	JDW	DRAWING STATUS: Released		
DATE:	07/17/18	PRODUCTION APPROVED FOR RELEASED STATUS ONLY		

FORM FEG035_PL_ASIZE, REV. B