


LUBRICATE ALL SEALS WITH CLEAN HYDRAULIC OIL PRIOR TO ASSEMBLY.
DO NOT USE SILICONE BASED LUBRICANTS.



No.	QTY	PART No.	DESCRIPTION	Repair Kit
N/A	N/A	62708004	REPAIR KIT	NOTED
5	4	39010061	BU RING, (-010)	X
4	3	39000021	O-RING, (-018)	X
3	4	31050012	DIFFUSER, DISK, SAE 4	X
2	2	31050009	FILTER, DISC, SAE 4, 25 MICRON	X
1	2	23002017	RETAINING RING, INTERNAL, 10 MM	X

PARTS LIST



VEKTEK, INC.
1334 E. SIXTH AVE. P.O. BOX 625
EMPORIA, KS. 66801 U.S.A.

ASSEMBLIES AFFECTED
70-8420-05
70-8420-06

PARTS LIST, ASSY, PLATE, FILTERED, PD, BOTTOM & REAR, INCH

SIZE
A PL7246

REV
A

SHEET 1 OF 1

A	3538	RELEASE	JDW	08/28/18
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY:	JDW	DRAWING STATUS: Released		
DATE:	08/28/18	PRODUCTION APPROVED FOR RELEASED STATUS ONLY		

FORM FEG035_PL_ASIZE, REV. B