


Lubricate all seals with clean hydraulic oil.  
DO NOT USE SILICONE BASED LUBRICANTS

REPAIR KIT	
60-7050-00	
39-0200-11	
70-5400-21	
39-0500-08	
39-0100-33	
39-0000-29	

No.	QTY	PART No.	DESCRIPTION
15	1	87054070	FITTING, END, PLV
14	1	87054041	MANIFOLD, PLV/PRV, MM
13	1	87054030	STOP, SPRING, PLV
12	1	87054000	BODY, CARTRIDGE, PLV
11	1	70540021	ASSEMBLY, POPPET, PLV
10	1	39050008	O-RING, (-014)
9	1	39020011	WASHER, COPPER, .360 X .500 X .032
8	1	39010033	BU RING, (-014)
7	2	39000050	O-RING, (-204)
6	1	39000029	O-RING, (-115)
5	1	30601199	PLUG, SOCH, SAE 10
4	3	30601144	PLUG, SOCH, SAE 4
3	2	30601122	PLUG, SOCH, SAE 2
2	1	23313015	SPRING, COMPRESSION
1	1	21440004	SHSS, HOLLOW

<b>PARTS LIST</b>	 VEKTEK, INC. 1334 E. SIXTH AVE. P.O. BOX 625 EMPORIA, KS. 66801 U.S.A.
	<b>PARTS LIST, ASSY, PLV, 500-2000, MANIFOLD</b>
Model Number 70-5400-08	SIZE A
	PL-7012
	REV H

H	5611	Released	ALS	1/20/25
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY:	VANDALSEM	<b>DRAWING STATUS: ECN</b>		
DATE:	10-30-89	PRODUCTION APPROVED FOR RELEASED STATUS ONLY		