



LUBRICATE ALL SEALS WITH CLEAN HYDRAULIC OIL PRIOR TO ASSEMBLY.
DO NOT USE SILICONE BASED LUBRICANTS.



PLATE
NON-REPLACEMENT PART



No.	QTY	PART No.	DESCRIPTION	NOTED
N/A	N/A	62708002	REPAIR KIT	NOTED
5	4	39010061	BU RING, (-010)	X
4	2	39000039	O-RING, (-014)	X
3	4	31050012	DIFFUSER, DISK, SAE 4	X
2	2	31050009	FILTER, DISC, SAE 4, 25 MICRON	X
1	2	23002017	RETAINING RING, INTERNAL, 10 MM	X
				Repair Kit

PARTS LIST



VEKTEK, INC.
1334 E. SIXTH AVE. P.O. BOX 625
EMPORIA, KS. 66801 U.S.A.

ASSEMBLIES AFFECTED
70-8427-70

PARTS LIST, PLATE, FILTERED, SV & PRV

SIZE
A PL7245

REV
A

SHEET 1 OF 1

A	5787	RELEASE	JHUBER	8/18/2025
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY:	JDH	DRAWING STATUS: Released		
DATE:	8/4/2025	PRODUCTION APPROVED FOR RELEASED STATUS ONLY		

FORM FEG035_PL_ASIZE, REV. B