


LUBRICATE ALL SEALS WITH CLEAN HYDRAULIC OIL PRIOR TO ASSEMBLY.
DO NOT USE SILICONE BASED LUBRICANTS.



N/A	N/A	62708002	REPAIR KIT	NOTED
5	4	39010061	BU RING, (-010)	X
4	2	39000039	O-RING, (-014)	X
3	4	31050012	DIFFUSER, DISK, SAE 4	X
2	2	31050009	FILTER, DISC, SAE 4, 25 MICRON	X
1	2	23002017	RETAINING RING, INTERNAL, 10 MM	X
No.	QTY	PART No.	DESCRIPTION	Repair Kit

PARTS LIST



VEKTEK, INC.
1334 E. SIXTH AVE. P.O. BOX 625
EMPORIA, KS. 66801 U.S.A.

A	3538	RELEASE	JDW	07/17/18
REV	IN ACCORDANCE WITH ECN	EFFECTIVE DATE	REVISED BY	DATE
DRW BY: JDW	DRAWING STATUS: Released PRODUCTION APPROVED FOR RELEASED STATUS ONLY			
DATE: 07/17/18				

ASSEMBLIES AFFECTED
47-0842-04

SIZE A	MPLV7245	REV A
-----------	----------	----------

FORM FEG035_PL_A SIZE, REV. B

SHEET 1 OF 1